

## SSA3000X Plus Firmware Revision History

| Version                   | Revision   |
|---------------------------|--|
| V3.2.2.6.0R7<br>2023/6/8  | <p>Notice:</p> <p>This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.</p> <p>New Functionality:</p> <ul style="list-style-type: none"> <li>Add PM demodulation in MA mode</li> <li>The time of analog demodulation in MA mode is adjustable</li> </ul> <p>Improvements:</p> <ul style="list-style-type: none"> <li>SCPI command for setting/obtaining the demodulation type:<br/>ADEMod:STYLE, new parameter is PM</li> <li>SCPI command for setting the scan time in MA mode<br/>[:SENSe]:SWEep:TIME</li> <li>Add SCPI commands in MA mode:<br/>Get AM parameters: FETCh:AM#?<br/>Get FM parameters: FETCh:FM#?<br/>Get PM parameters: FETCh:PM#?</li> <li>Add SCPI command:<br/>Exit remote status: SYSTem: LOCal</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>Fix the problem that the bandwidth of the emi filter in SA mode</li> <li>Fix the problem that setting the TG Level in SA mode may cause TG to have no output</li> <li>Fix the problem that the n dB Marker measurement results in SA mode are inconsistent with the OBW measurement results</li> <li>Fix the problem that there is an invalid frequency menu in Harmonic in SA mode</li> <li>Fix the abnormality of the first scan in EMI mode</li> <li>Fix the problem that setting rbw may crash when qpd is not enabled in EMI mode</li> <li>Fix an issue where 'micro' relative units represented by 'u' were not recognized when reading files</li> </ul> |
| V3.2.2.5.1R1<br>2022/5/10 | <p>Notice:</p> <p>This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.</p> <p>Improvements:</p> <ul style="list-style-type: none"> <li>Optimize the Ref level and Att couple</li> <li>Add SCPI commands in MA Mode <ul style="list-style-type: none"> <li>•READ:ADEMod:AVG?</li> <li>•[:SENSe]:ADEMod:FM:DEVI?</li> <li>•[:SENSe]:ADEMod:FM:DRIFT?</li> </ul> </li> </ul>   |

| Version                    | Revision  |
|----------------------------|---|
|                            | <ul style="list-style-type: none"> <li>•[:SENSe]:BWIDth[:RESolution]</li> <li>•[:SENSe]:BWIDth[:RESolution]?</li> <li>•[:SENSe]:BWIDth:EQLPf</li> <li>•[:SENSe]:BWIDth:EQLPf?</li> <li>•CALCulate:MARKer#:PTPeak</li> <li>• Add .trc file in EMI Mode</li> <li>• Add .lic file auto scan</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>• Fix pi/4 DPSK 和 pi/8 DPSK decode errors in MA mode</li> <li>• Fix fft frequency error in narrow span in SA mode</li> <li>• Fix trace avg calculation error in SA mode</li> <li>• Fix the zero sweep type when fft in SA mode</li> </ul>  |
| V3.2.2.5.0<br>2021/9/30    | <p>Notice:</p> <p>This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.</p> <p>New Functionality:</p> <ul style="list-style-type: none"> <li>• Add Ext Trigger Delay from 0-10 seconds in SA Mode</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>• SA fix the difference between marker and peak and marker style; Fix Center Freq error; Fix limit fail to stop error; Fix Auto frequency error; In normalization, auto re-normalized after any setting changes</li> <li>• EMI frequency offset error; saving std lim path error</li> <li>• Web browser cannot change IP, and cannot login after changing password</li> </ul> |
| V3.2.2.4.0<br>2021/1/15    | <p>This version can not be rolled back</p> <ul style="list-style-type: none"> <li>• Fix TG switch error at small RBW</li> <li>• Fix Help and Limit file lost when Factory reset</li> <li>• Fix CNR calc error when no peak found</li> <li>• Fix OBW result overflow</li> <li>• Fix Harmonic calc error at 100Hz RBW</li> <li>• Fix Reflection Open+Short calibration action</li> <li>• Fix spectrum amplitude error in DMA mode</li> <li>• Optimize EMI .csv file content to all signal list</li> <li>• Optimize EMI peak search</li> <li>• Optimize Auto cal process</li> <li>• Add Peak search to Spectrum in DMA mode</li> </ul>   |
| V3.2.2.3.3R1<br>2020/12/01 | <p>New Functionality:</p>   |

| Version                  | Revision  |
|--------------------------|---|
|                          | <ul style="list-style-type: none"> <li>Add EMI filter in SA for EMI option</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>Optimize the TG flatness and control procedure</li> <li>Optimize Help</li> <li>Fix Correction, .csv file, add peak numbers to 20 in EMI mode</li> <li>Fix amplitude error in DMA Mode</li> <li>Fix upgrade failure issue</li> </ul>  |
| V3.2.2.3.2<br>2020/09/09 | <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>Fix avg power bug in EMI Mode</li> <li>Fix amplitude bug in AMA Mode</li> <li>Fix peak search bug in SCPI command</li> </ul>   |
| V2.2.1.2.8<br>2020/06/30 | <p>New Functionality:</p> <ul style="list-style-type: none"> <li>Update EMI option to a new EMI measurement mode</li> </ul> <p>Improvements:</p> <ul style="list-style-type: none"> <li>Improve TG output harmonic performance</li> <li>Update Help file</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>Fix ADC overload warning</li> <li>Fix Ch Power calculation bug in small span</li> </ul>  |
| V2.2.1.2.7<br>2020/05/12 | <p>Improvements:</p> <ul style="list-style-type: none"> <li>Add Limit mask offset in SA mode</li> <li>TG Level adjustable in Reflection Meas</li> </ul> <p>Solved Issues:</p> <ul style="list-style-type: none"> <li>Fixed AM and FM symbol rate error, Lpf coefficient error, in AMA mode</li> <li>Fixed Filter bandwidth error in DMA mode</li> <li>Fixed Freq counter error in SA mode</li> <li>Fixed Harmonic error in SA mode</li> <li>Help Display error</li> </ul> |
| V2.2.1.2.5<br>2019/11/11 | <p>Improvements:</p> <ul style="list-style-type: none"> <li>Optimize trace, marker, signal track, TG normalization, Reflection measurement in SA Mode</li> <li>Optimize web server UI</li> </ul>  |

| Version | Revision   |
|---------|--|
|         | <p>Solved Issues:</p> <ul style="list-style-type: none"><li>• Fixed video trigger fail, errors in Harmonic measurement in SA Mode</li><li>• Fixed spectrum amplitude error, meas error, waveform discontinue in MA Mode</li><li>• Fixed English help, system message</li></ul> |
|         |  |