

Revision History

Date	Version	Revision
2019/1/30	3.01.01.06R2	<ol style="list-style-type: none">1. Add DHCP function to IP addressing2. Add Open Socket at LAN port 50253. Add over current protect function in a special case4. Fix a crash fault when restoring settings5. Modify the calibration arithmetic in 2-wire resistance measurement 10 MOhm range6. Add "ABORT BULK IN" , "INITIATE CLEAR" features to remote SCPI commands
2017/4/06	3.01.01.03	<ol style="list-style-type: none">1. Add U disk recovery function2. Add the update of the calibration data function3. Fix the bug of a few abnormal DCV measurements when the input terminal is shorted4. Repair the external trigger problem5. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 50246. FPGA optimization