

SSA3000X Firmware Revision History

Version	Revision
V2.1.1.3R1 2022/6/10	<p>Notice:</p> <p>This firmware must be upgraded from v2.1.1.1 or later. If your analyzer has an earlier version, don't use this FW to update.</p> <p>Improvements:</p> <ul style="list-style-type: none">• Optimize the Ref level and Att couple <p>Solved Issues:</p> <ul style="list-style-type: none">• Fix the zero sweep type when fft in SA mode• Fix the OPC response in EMI mode
V2.1.1.1 2022/4/7	<ol style="list-style-type: none">1. The V2 version is the first time introduced.2. It was not able to update from any earlier version (V1.X.X.X) and it also can not downgrade to the earlier version